

Software Release Notes



Product: XRS2i and SRS2i Firmware

Version: 1.4.11.34

XRS2i and SRS2i –Main Version v1.4.11.34 – BT version 1.1.4

New features

- Added possibility to enable Bluetooth auto-reconnection when in HID mode (“Auto” mode enables it, “Manual” disables it). iPhone users may have to reconnect the device from the phone Bluetooth settings.
- Removed unused options from Bluetooth menu when using HID mode, to avoid user errors
- Added Bluetooth module firmware version in “General” settings menu

Bug fixes

- Fixed Bluetooth barcode scanner support for Zebra devices
- Fixed Bluetooth connection to the following Barcode Printers (Only XRS2i):
 - Zebra ZQ511
 - Zebra QNL320
- Fixed Bluetooth connection with Datalink app
- Fixed Bluetooth connection with smartphones/tablets/PCs
- Fixed lock-up situation when reading in continuous mode
- Fixed issue with receiving weights from JR/ID/XR5000

XRS2i and SRS2i –Main Version v1.4.11.16, BT version 1.1.2

New features

- Added possibility to input barcode into VID

Bug fixes

- Fixed Bluetooth barcode scanner support
- Fixed auto power off issue
- Fixed HID extra digits issue
- Fixed user interface bug in Session Record screen